


# 1978 SR

## PARTS DIAGRAM

### GENERATOR/STARTER MOTOR



# 1978 SR

## PARTS LIST

### GENERATOR/STARTER MOTOR

| ITEM NAME                       | PART NUMBER | QUANTITY |
|---------------------------------|-------------|----------|
| COVER,STARTER (Ref # 1)         | 21165-003   | 1        |
| GASKET,STARTER COVER (Ref # 2)  | 21166-003   | 1        |
| BOLT (6X10) (Ref # 3)           | 110R0610    | 1        |
| STARTER-ELECTRIC (Ref # 4)      | 21163-1022  | 1        |
| "0" RING,62MM (Ref # 5)         | 21027-006   | 1        |
| WASHER,THRUST,0.2T (Ref # 6)    | 21025-011   | 1        |
| WASHER,THRUST,1.6T (Ref # 7)    | 21025-010   | 1        |
| CARBON BRUSH (Ref # 8)          | 21039-003   | 1        |
| SPRING,CARBON BRUSH (Ref # 9)   | 21040-003   | 1        |
| "0" RING,40M/M (Ref # 10)       | 21027-008   | 1        |
| CIRCLIP (Ref # 11)              | 92033-034   | 1        |
| PINION,STARTER (Ref # 12)       | 21053-004   | 1        |
| CIRCLIP,13M/M (Ref # 13)        | 92033-037   | 1        |
| WIRE-LEAD,STARTER (Ref # 14)    | 26011-1099  | 1        |
| CAP,STARTING MOTOR (Ref # 15)   | 21017-020   | 1        |
| NUT 6MM (Ref # 16)              | 312B0600    | 1        |
| WASHER SPRING 6MM (Ref # 17)    | 461F0600    | 1        |
| SCREW,PAN HEAD,6X130 (Ref # 18) | 21099-006   | 1        |
| BOLT-UPSET (Ref # 19)           | 112G0660    | 1        |
| BOLT,10X40 (Ref # 20)           | 92001-1201  | 1        |
| STATOR (Ref # 21)               | 21003-1005  | 1        |
| BOLT-SOCKET,5X30 (Ref # 22)     | 120P0530    | 1        |
| FLYWHEEL (Ref # 23)             | 21050-1003  | 1        |
| CLAMP,GENERATOR WIRE (Ref # 24) | 92037-1122  | 1        |
| SCREW PAN HEAD 5X12 (Ref # 25)  | 220B0512    | 1        |
| WASHER SPRING 5MM (Ref # 26)    | 461F0500    | 1        |
| WASHER,PLAIN,6MM (Ref # 27)     | 410D0600    | 1        |