


1983 GPz 1100 PARTS DIAGRAM

CABLES

F2540-0202



1983 GPz 1100 PARTS LIST

CABLES

ITEM NAME	PART NUMBER	QUANTITY
CABLE-SPEEDOMETER (Ref # 54001)	54001-1048	1
CABLE-CLUTCH (Ref # 54011)	54011-1169	1
CABLE-THROTTLE (Ref # 54012)	54012-1111	1
CLAMP,CABLE (Ref # 92037)	92037-093	1
CLAMP,CLUTCH CABLE (Ref # 92037A)	92037-1457	1
CLAMP,THROTTLE (Ref # 92037B)	92037-1463	1