


## 1984 Prairie® 250 PARTS DIAGRAM

STARTER MOTOR STARTER CLUTCH ('84-'85 C2)

E1840-0043



1  
1  
1  
2  
2  
2  
2  
5  
5  
5  
5  
5  
5  
5  
5  
5  
5  
5

## 1984 Prairie® 250 PARTS LIST

STARTER MOTOR STARTER CLUTCH ('84-'85 C2)

ITEM NAME	PART NUMBER	QUANTITY
SPROCKET,STARTER MOTO (Ref # 12046)	12046-1004	1
SPROCKET,STARTER (Ref # 12046A)	12046-1023	1
PLATE (Ref # 13169)	13169-1010	1
CLUTCH ASSY,STARTING (Ref # 13193)	13193-1006	1
BRUSH,CARBON (Ref # 21039)	21039-1053	1
SPRING-BRUSH (Ref # 21040)	21040-1003	1
STARTER-ELECTRIC (Ref # 21163)	21163-1036	1
WIRE-LEAD,STARTER MOT (Ref # 26011)	26011-1201	1
SWITCH,STARTER (Ref # 27010)	27010-1314	1
SCREW,PAN HEAD,6X130 (Ref # 92001)	92001-1046	1
BOLT (Ref # 92001A)	120P0816	1
NUT-6MM (Ref # 92015)	92015-1078	2
WASHER,THRUST,0.2T (Ref # 92022)	21025-011	1
WASHER,PLAIN (Ref # 92022A)	92022-1108	1
WASHER,THRUST,0.8T (Ref # 92022B)	92022-1132	1
CIRCLIP,13M/M (Ref # 92033)	92033-037	1
PIN (Ref # 92043)	92043-087	1
"O" RING,42.8MM (Ref # 92055)	21027-005	1
"O" RING,STARTER MOTR (Ref # 92055A)	92055-1086	1
CHAIN,DYNAMO (Ref # 92057)	92057-1009	1
GROMMET,CORD (Ref # 92071)	21017-017	1
SPRING (Ref # 92081)	92081-110	1
PIN (Ref # 92122)	92122-001	1
BOLT-UPSET-WP (Ref # 186)	186G0625	1
SCREW PAN HEAD 6X14 (Ref # 220)	220B0614	1
WASHER SPRING 6MM (Ref # 461)	461F0600	1