


# 2012 W800 (European)

## PARTS DIAGRAM

### Swingarm

F2141



# 2012 W800 (European)

## PARTS LIST

### Swingarm

| ITEM NAME                               | PART NUMBER | QUANTITY |
|-----------------------------------------|-------------|----------|
| NUT-HEX-SMALL,8MM (Ref # 317)           | 317BA0800   | 2        |
| BEARING-BALL,#6203 (Ref # 601)          | 601A6203    | 1        |
| ARM-COMP-SWING (Ref # 33001)            | 33001-0566  | 1        |
| SHAFT-SWING ARM (Ref # 33032)           | 33032-1192  | 1        |
| ADJUSTER-CHAIN (Ref # 33040)            | 33040-0076  | 2        |
| SLEEVE,SWING ARM,L=186.6 (Ref # 42036)  | 42036-1352  | 1        |
| GUARD,CHAIN (Ref # 55020)               | 55020-1686  | 1        |
| SCREW,6X18 (Ref # 92009)                | 92009-1663  | 1        |
| NUT,POP,6MM,L=15 (Ref # 92015)          | 92015-1791  | 1        |
| COLLAR,L=4.5 (Ref # 92027)              | 92027-1965  | 1        |
| RING-SNAP,40MM (Ref # 92033)            | 92033-1040  | 1        |
| BEARING-NEEDLE,BHTM2530-1 (Ref # 92046) | 92046-1035  | 2        |
| SEAL-OIL (Ref # 92049)                  | 92049-1047  | 1        |
| SEAL-OIL,MH25334 (Ref # 92049A)         | 92049-1060  | 1        |
| COLLAR,RR AXLE,L=14 (Ref # 92143)       | 92143-1188  | 1        |
| BOLT,8X55 (Ref # 92153)                 | 92153-1407  | 2        |
| NUT,PIVOT,16MM (Ref # 92210)            | 92210-1077  | 1        |