


# 1992 Jet Mate

## PARTS DIAGRAM

Tool

(F3182



# 1992 Jet Mate

## PARTS LIST

### Tool

ITEM NAME	PART NUMBER	QUANTITY
FUSE,20A,L=31.8 (Ref # 26006)	26006-3701	1
FUSE,5A,L=31.8 (Ref # 26006A)	26006-3702	1
TOOLKIT (Ref # 56007)	56007-3708	1
BAG,TOOL (Ref # 56008)	56008-1007	1
TOOL-DRIVER,#3PHILLIPS (Ref # 92107)	92107-005	1
TOOL-DRIVER,#2PHILLIPS&SLOT (Ref # 92107A)	92107-1051	1
TOOL-WRENCH,ALLEN,5MM (Ref # 92110)	92110-1015	1
TOOL-WRENCH,BOX,21MM (Ref # 92110A)	92110-1113	1
TOOL-WRENCH,OPEN END,10X12 (Ref # 92110B)	92110-1152	1
TOOL-WRENCH,OPEN END,14X17 (Ref # 92110C)	92110-1153	1
TOOL-WRENCH,OPEN END,8X10 (Ref # 92110D)	92126-001	1
TOOL-PLIERS (Ref # 92112)	92112-003	1
TOOL-WRENCH,ALLEN,8MM (Ref # 92127)	92127-002	1