


1982 AR50-A1 PARTS DIAGRAM

CABLES

F2540-0049



1982 AR50-A1 PARTS LIST

CABLES

ITEM NAME	PART NUMBER	QUANTITY
CABLE,SPEEDOMETER (Ref # 54001)	54001-1031	1
CABLE-CLUTCH (Ref # 54011)	54011-1108	1
CABLE-THROTTLE (Ref # 54012)	54012-1097	1
CABLE-TACHOMETER (Ref # 54018)	54018-1013	1
CLAMP,SPEEDOMETER CAB (Ref # 92037)	92037-1263	1
CLAMP (Ref # 92037A)	92037-1275	1
GROMMET,OIL TUBE (Ref # 92071)	92071-1029	1
BAND,MIDDLE (Ref # 92072)	92072-031	1
BOLT-UPSET,6X16 (Ref # 110)	112G0616	1
WASHER PLAIN 6MM (Ref # 411)	411B0600	1
WASHER SPRING 6MM (Ref # 461)	461F0600	1