


1982 AR50-A1 PARTS DIAGRAM

TURN SIGNALS

F2730-0088



1982 AR50-A1 PARTS LIST

TURN SIGNALS

ITEM NAME	PART NUMBER	QUANTITY
GASKET,SGNL LAMP LENS (Ref # 11009)	11009-1128	1
LAMP-SIGNAL (Ref # 23040)	23040-1049	1
LENS-SIGNAL LAMP (Ref # 23048)	23048-1076	1
BRACKET-SIGNAL LAMP,F (Ref # 23051)	23051-1039	1
BRACKET-SIGNAL LAMP,F (Ref # 23051A)	23051-1040	1
BRACKET-SIGNAL LAMP,L (Ref # 23051B)	23051-1044	1
BRACKET-SIGNAL LAMP,R (Ref # 23051C)	23051-1045	1
SCREW,TAPPING (Ref # 92009)	92009-1056	1
BULB,6V 21CP (Ref # 92069)	92069-056	1
WASHER-PLAIN,4MM (Ref # 92075)	23058-002	1
BOLT-UPSET,6X16 (Ref # 110)	112G0616	1
NUT,5MM (Ref # 311)	311B0500	1