


1972 Mach II

PARTS DIAGRAM

CYLINDER HEADS/CYLINDERS

Ref.



1
1
1
1
1
1
1
1
1
1

1972 Mach II

PARTS LIST

CYLINDER HEADS/CYLINDERS

ITEM NAME	PART NUMBER	QUANTITY
NUT,8MM (Ref # 1)	311B0800	12
WASHER SPRING 8MM (Ref # 2)	461F0800	12
UNAVAILABLE IN PRICE BOOK (Ref # 3)	92070-011A	1
CYLINDER HEAD,BUFF (Ref # 4)	11001-053-80	2
CYLINDER HEAD,CENTER (Ref # 5)	11001-054	1
GASKET-CYLINDER HEAD (Ref # 6)	11004-043	3
CYLINDER,L.H (Ref # 7)	11005-068	1
CYLINDER-CENTER (Ref # 8)	11005-069	1
CYLINDER,R.H (Ref # 9)	11005-070	1
GASKET-CYLINDER BASE (Ref # 10)	11009-027	3
STUD 8X20 (Ref # 11)	172G0820	6
GASKET-AIR INLET (Ref # 12)	16062-014	6
INSULATOR-HEAT (Ref # 13)	16061-012	3
INLET-AIR (Ref # 14)	16060-012	3
WASHER SPRING 8MM (Ref # 15)	461F0800	6
NUT,8MM (Ref # 16)	311B0800	6
STUD,8X35 (Ref # 17)	92004-1009	6
GASKET,EXHAUST PIPE (Ref # 18)	11009-1992	3
GASKET,EXHAUST PIPE (Ref # 18)	11009-1992	3