


1979 KZ400-H1 PARTS DIAGRAM

TURN SIGNALS



1979 KZ400-H1 PARTS LIST

TURN SIGNALS

ITEM NAME	PART NUMBER	QUANTITY
LAMP ASSY,TURN SIGNAL (Ref # 1)	23040-1018	4
GASKET,TURN SIGNAL (Ref # 2)	11009-1052	4
SCREW-PAN-CROS (Ref # 3)	220E0412	8
LENS-SIGNAL LAMP (Ref # 4)	23048-1022	4
WASHER-PLAIN,4MM (Ref # 5)	23058-002	8
BULB 12V 32CP (Ref # 6)	92069-055	4
BRACKET,TURN SIGNAL (Ref # 7)	23051-1014	2
BOLT-UPSET (Ref # 8)	112G0630	4
NUT 6MM (Ref # 9)	311B0600	4
WASHER PLAIN 6MM (Ref # 10)	411B0600	8
WASHER SPRING 6MM (Ref # 11)	461F0600	4
BRACKET,SIGNAL LAMP,F (Ref # 12)	23051-1022	2
NUT 10MM (Ref # 13)	315B1000	4
WASHER SPRING 10MM (Ref # 14)	461F1000	4
COLLAR (Ref # 15)	92027-147	2
DAMPER RUBBER (Ref # 16)	92075-128	2
DAMPER RUBBER,SIG LM (Ref # 17)	92075-158	2
WASHER-PLAIN,10MM (Ref # 18)	411D1000	2