


1981 KZ1000-J1 PARTS DIAGRAM

TURN SIGNALS



F2730-0095



1981 KZ1000-J1 PARTS LIST

TURN SIGNALS

ITEM NAME	PART NUMBER	QUANTITY
GASKET,SIGNAL LAMP (Ref # 11009)	11009-1150	1
LAMP-ASSY-SIGNAL,FR (Ref # 23037)	23037-1131	1
LAMP-ASSY-SIGNAL (Ref # 23037A)	23037-1104	1
LENS-SIGNAL LAMP (Ref # 23048)	23048-1019	1
SCREW,TAPPING,4X25 (Ref # 92009)	92009-1069	1
NUT,FLANGED,10MM (Ref # 92015)	92015-1428	1
WASHER,10.5X37X1.6 (Ref # 92022)	92022-1246	1
BULB 12V 32CP (Ref # 92069)	92069-055	1
BULB,12V 23/8W (Ref # 92069A)	92069-060	1
WASHER-PLAIN,4MM (Ref # 92075)	23058-002	1
DAMPER,SIGNAL LAMP (Ref # 92075A)	92075-1391	1