


# 1982 KDX80 PARTS DIAGRAM

SWING ARM

F2140-0032



# 1982 KDX80 PARTS LIST

## SWING ARM

| ITEM NAME                         | PART NUMBER | QUANTITY |
|-----------------------------------|-------------|----------|
| CAP,SWING ARM (Ref # 11012)       | 11012-1150  | 4        |
| GUIDE,CHAIN (Ref # 12053)         | 12053-1053  | 1        |
| GUIDE,CHAIN (Ref # 12053A)        | 12053-1057  | 1        |
| ARM,SWING (Ref # 33001)           | 33001-1074  | 1        |
| SHAFT,SWING ARM (Ref # 33032)     | 33032-1017  | 1        |
| ADJUSTER,CHAIN (Ref # 33040)      | 33040-1009  | 2        |
| SLEEVE,CHAIN GUIDE (Ref # 42036)  | 42036-1042  | 2        |
| GUARD,CHAIN (Ref # 55020)         | 55020-1047  | 1        |
| GUARD,CHAIN (Ref # 55020A)        | 55020-1055  | 1        |
| BOLT,6X38 (Ref # 92001)           | 92001-1463  | 2        |
| NUT,LOCK 6MM (Ref # 92015)        | 92017-014   | 4        |
| NUT-LOCK,14MM (Ref # 92015A)      | 92019-011   | 1        |
| WASHER 6.5X20X1.6T (Ref # 92022)  | 92022-125   | 3        |
| COLLAR (Ref # 92027)              | 92027-1260  | 1        |
| COLLAR,CHAIN GUIDE (Ref # 92027A) | 92027-1332  | 1        |
| BEARING-NEEDLE (Ref # 92046)      | 92046-1162  | 2        |
| BOLT-UPSET,6X16 (Ref # 110)       | 112G0616    | 2        |
| BOLT-UPSET (Ref # 110A)           | 112G0645    | 2        |
| BOLT,FLANGED,6X40 (Ref # 130)     | 130B0640    | 2        |
| NUT 6MM (Ref # 311)               | 311B0600    | 2        |
| WASHER PLAIN 6MM (Ref # 411)      | 411B0600    | 2        |
| WASHER SPRING 6MM (Ref # 461)     | 461F0600    | 2        |