


# 1999 1100 STX PARTS DIAGRAM

Carburetor

E1611



# 1999 1100 STX PARTS LIST

## Carburetor

ITEM NAME	PART NUMBER	QUANTITY
CARBURETOR-ASSY (Ref # 15003)	15003-3728	1
SCREW-THROTTLE STOP (Ref # 16021)	16021-3704	2
SCREW-THROTTLE STOP (Ref # 16021A)	16021-3707	1
JOINT (Ref # 59071)	59071-3762	4
FITTING (Ref # 92005)	92005-3729	2
SCREW,5X28 (Ref # 92009)	92009-3783	4
SCREW,4X6 (Ref # 92009A)	92009-3786	1
CLAMP (Ref # 92037)	92037-1173	2
RING-O (Ref # 92055)	92055-1246	16
SPRING,ADJUST SCREW (Ref # 92144)	92144-3704	2
SPRING,THROTTLE STOP SCREW (Ref # 92144A)	92144-3745	2
TUBE (Ref # 92191)	92191-3852	1