


2013 Z1000 PARTS DIAGRAM

Swingarm



2013 Z1000 PARTS LIST

Swingarm

ITEM NAME	PART NUMBER	QUANTITY
ARM-COMP-SWING,F.S.BLACK (Ref # 33001)	33001-0229-18R	1
SHAFT-SWING ARM (Ref # 33032)	33032-0013	1
SLEEVE,20.1X28X226 (Ref # 42036)	42036-0069	1
SLEEVE,REAR AXLE,LH,SILVER (Ref # 42036B)	42036-1153-KX	1
SLEEVE,REAR AXLE,RH,SILVER (Ref # 42036D)	42036-1265-KX	1
GUARD,CHAIN (Ref # 55020)	55020-0549	1
BOLT,6X12 (Ref # 92001)	92001-1771	1
RING-SNAP,42MM (Ref # 92033)	92033-1041	1
BEARING-BALL,6004UL11 (Ref # 92045)	92045-0017	1
BEARING-NEEDLE,7E-HVS 28X34X17 (Ref # 92046)	92046-0008	3
SEAL-OIL,MHSA25X42X6 (Ref # 92049)	92049-1314	1
SEAL-OIL,MHSA25X34X7 (Ref # 92049A)	92049-1352	1
BOLT,SOCKET,10X40 (Ref # 92151)	92151-1899	2
COLLAR,SWING ARM,L=47 (Ref # 92152)	92152-0154	1
COLLAR,SWING ARM,L=12.5 (Ref # 92152A)	92152-1234	1
CLAMP (Ref # 92171)	92171-0907	1
WASHER,10.5X18X2.3 (Ref # 92200)	92200-0531	2
NUT,30MM (Ref # 92210)	92210-0134	1
NUT,FLANGED,20MM (Ref # 92210A)	92210-0320	1
NUT,POP,6MM,L=15 (Ref # 92210B)	92210-1397	1