


2011 Z1000 PARTS DIAGRAM

Turn Signals



2011 Z1000 PARTS LIST

Turn Signals

ITEM NAME	PART NUMBER	QUANTITY
SCREW-PAN-WP-CROS,4X8 (Ref # 224)	224AB0408	2
SOCKET-ASSY,SIGNAL LAMP,FR (Ref # 23008)	23008-0044	2
LAMP-ASSY-SIGNAL,RR,LH (Ref # 23037)	23037-0165	1
LAMP-ASSY-SIGNAL,RR,RH (Ref # 23037A)	23037-0171	1
LAMP-SIGNAL,FR,LH (Ref # 23040)	23040-0057	1
LAMP-SIGNAL,FR,RH (Ref # 23040A)	23040-0058	1
LENS-SIGNAL LAMP,RR,LH (Ref # 23048)	23048-0014	1
LENS-SIGNAL LAMP,RR,RH (Ref # 23048A)	23048-0015	1
BULB,12V 10W (Ref # 92069)	92069-0024	2
BULB,12V 21W (Ref # 92069A)	92069-1125	2
SCREW,TAPPING,5X16 (Ref # 92172)	92172-0175	6
SCREW,2.9X22 (Ref # 92172A)	92172-0395	2
WASHER,SIGNAL LAMP (Ref # 92200)	92200-0164	2
WASHER,SIGNAL LAMP (Ref # 92200A)	92200-0165	2