


Let the good times roll®

1988 KDX200 PARTS DIAGRAM

Swingarm

F2141-0033



1988 KDX200 PARTS LIST

Swingarm

ITEM NAME	PART NUMBER	QUANTITY
CAP,SWING ARM (Ref # 11012)	11012-1259	4
BRACKET (Ref # 11046)	11045-1922	1
GUIDE-CHAIN,RR,INSIDE (Ref # 12053A)	12053-1105	1
GUIDE-CHAIN,RR (Ref # 12053B)	12053-1124	1
GUIDE-CHAIN,FR,LWR (Ref # 12053D)	12053-1208	1
GUIDE-CHAIN,FR,UPP (Ref # 12053E)	12053-1213	1
GUIDE,LH (Ref # 13070)	13070-1141	1
GUIDE,RH (Ref # 13070A)	13070-1142	1
ARM-COMP-SWING (Ref # 33001B)	33001-1305	1
SHAFT-SWING ARM (Ref # 33032A)	33032-1138	1
ADJUSTER-CHAIN (Ref # 33040)	33040-1067	1
SLEEVE,L=36 (Ref # 42036)	42036-1171	2
NUT,FLANGED,14MM (Ref # 92015)	92015-1032	1
NUT,FLANGED,6MM (Ref # 92015A)	92015-1078	2
PIN,6X17 (Ref # 92043)	92043-107	2
BEARING-NEEDLE,TA2030Z (Ref # 92046)	92046-1128	2
BOLT,FLANGED,6X52 (Ref # 92150)	92150-1001	4
BOLT-FLANGED-SMALL (Ref # 132)	132G0610	2
SCREW-CSK-CROS,6X10 (Ref # 221)	221B0610	4
WASHER-PLAIN-SMALL,6MM (Ref # 410)	410B0600	2
PIN-COTTER,2.0X15 (Ref # 550)	550D2015	2