



1996 KDX200 PARTS DIAGRAM

Meter(s)

F2530



1996 KDX200 PARTS LIST

Meter(s)

| ITEM NAME | PART NUMBER | QUANTITY |
|---------------------------------------|-------------|----------|
| NUT-HEX (Ref # 311) | 311B0400 | 1 |
| SPEEDOMETER,TRIP(KM) (Ref # 25005) | 25005-1572 | 1 |
| SPEEDOMETER,TRIP(MILE) (Ref # 25005A) | 25005-1573 | 1 |
| BRACKET-METER (Ref # 25008) | 25008-1196 | 1 |
| WASHER,4.3X12.5X1 (Ref # 92022) | 92022-1888 | 1 |
| KNOB,TRIP (Ref # 92077) | 92077-1114 | 1 |
| DAMPER (Ref # 92160) | 92160-1569 | 1 |