


2003 Mojave 250 PARTS DIAGRAM

Swingarm

F2141



2003 Mojave 250 PARTS LIST

Swingarm

ITEM NAME	PART NUMBER	QUANTITY
BOLT-UPSET (Ref # 112)	112P1035	1
BOLT-FLANGED,6X40 (Ref # 130)	130G0640	1
BOLT-FLANGED (Ref # 130A)	130G0680	1
BOLT-UPSET-WS,6X14 (Ref # 180)	180G0614	1
SCREW-CSK-RD-CROS,6X12 (Ref # 222)	222B0612	1
WASHER-SPRING,10MM (Ref # 461)	461F1000	1
PIN-SNAP,10MM (Ref # 554)	554A1000	1
CAP,SWING ARM (Ref # 11012)	11012-1259	1
CAP,SWING ARM (Ref # 11012A)	11012-1520	1
GUIDE-CHAIN,UPP (Ref # 12053)	12053-1194	1
GUIDE-CHAIN,LWR (Ref # 12053A)	12053-1195	1
GUIDE,CHAIN (Ref # 13070)	13070-1156	1
ARM-COMP-SWING,G.GRAY (Ref # 33001A)	33001-1415-HN	1
SHAFT-SWING ARM (Ref # 33032)	33032-1139	1
SLEEVE,SWING ARM (Ref # 42036)	42036-1064	1
ROD,TORQUE,G.GRAY (Ref # 46102A)	46102-1342-HN	1
GUARD,CHAIN&DISC,G.GRAY (Ref # 55020A)	55020-1636-HN	1
BOLT,10X28 (Ref # 92002)	92002-1733	1
SCREW,6X10,WHITE (Ref # 92009)	92009-1286	1
NUT,14MM (Ref # 92015)	92015-1407	1
NUT,6MM (Ref # 92015A)	92015-1452	1
NUT,LOCK,10MM (Ref # 92015B)	92015-1597	1
WASHER,6.5X20X1.6 (Ref # 92022)	92022-1804	1
BUSHING,SWING ARM (Ref # 92028)	92028-1261	1
BEARING-NEEDLE,TA2030Z (Ref # 92046)	92046-1128	1