


2008 Z1000

PARTS DIAGRAM

Turn Signals



2008 Z1000

PARTS LIST

Turn Signals

ITEM NAME	PART NUMBER	QUANTITY
SCREW-PAN-WP-CROS,4X8 (Ref # 224)	224C0408	2
LENS-COMP,SIGNAL LAMP,RR,LH (Ref # 23007B)	23007-0102	1
LENS-COMP,SIGNAL LAMP,RR,RH (Ref # 23007C)	23007-0103	1
SOCKET-ASSY,SIGNAL LAMP,FR (Ref # 23008)	23008-0044	2
LAMP-ASSY-SIGNAL,RR,LH (Ref # 23037B)	23037-0129	1
LAMP-ASSY-SIGNAL,RR,RH (Ref # 23037C)	23037-0130	1
LAMP-SIGNAL,FR,LH (Ref # 23040)	23040-0057	1
LAMP-SIGNAL,FR,RH (Ref # 23040A)	23040-0058	1
SCREW,4X16,BLACK (Ref # 92009)	92009-1158	2
BULB,12V 10W (Ref # 92069A)	92069-0020	2
BULB,12V 21W (Ref # 92069B)	92069-1125	2
SCREW,TAPPING,5X16 (Ref # 92172)	92172-0175	6
WASHER,SIGNAL LAMP (Ref # 92200)	92200-0164	2
WASHER,SIGNAL LAMP (Ref # 92200A)	92200-0165	2