


## 1999 KX500 PARTS DIAGRAM

Transmission



## 1999 KX500 PARTS LIST

### Transmission

ITEM NAME	PART NUMBER	QUANTITY
SHAFT-TRANSMISSION INPUT,16T (Ref # 13127)	13127-1159	1
SHAFT-TRANSMISSION OUTPUT (Ref # 13128)	13128-1150	1
GEAR,OUTPUT LOW,32T (Ref # 13129)	13129-1180	1
GEAR,OUTPUT TOP,19T (Ref # 13129A)	13129-1575	1
GEAR,INPUT TOP,24T (Ref # 13129B)	13129-1744	1
SPROCKET-OUTPUT,15T (Ref # 13144)	13144-069	1
SPROCKET-OUTPUT,14T (Ref # 13144A)	13144-1005	1
SPROCKET-OUTPUT,13T (Ref # 13144B)	13144-1027	1
GEAR,INPUT 4TH,22T (Ref # 13260)	13260-1020	1
GEAR,OUTPUT 4TH,21T (Ref # 13260A)	13260-1021	1
GEAR,INPUT 2ND,18T (Ref # 13260B)	13260-1100	1
GEAR,INPUT 3RD,22T (Ref # 13260C)	13260-1101	1
GEAR,OUTPUT 2ND,26T (Ref # 13260D)	13260-1102	1
GEAR,OUTPUT 3RD,26T (Ref # 13260E)	13260-1103	1
WASHER,17.3X28X1 (Ref # 92022)	92022-255	1
RING-SNAP,24MM (Ref # 92033)	92033-026	1
RING-SNAP,18MM (Ref # 92033A)	92033-029	1
RING-SNAP,25MM (Ref # 92033B)	92033-1089	1
BEARING-NEEDLE,KT202614 (Ref # 92046)	92046-1170	1
RING-O (Ref # 92055)	92055-035	1
COLLAR,25X32X10.5 (Ref # 92143)	92143-1370	1