


Mule 600 PARTS DIAGRAM

Drive Converter



Mule 600 PARTS LIST

Drive Converter

ITEM NAME	PART NUMBER	QUANTITY
BOLT-FLANGED,8X30 (Ref # 130)	130S0830	4
COVER-COMP (Ref # 14041)	14041-0006	1
WEIGHT-RAMP (Ref # 39152)	39152-0011	4
SHOE,T=7.2 (Ref # 49048)	49048-1087	AR
SHOE,T=7.3 (Ref # 49048A)	49048-1088	AR
SHOE,T=7.4 (Ref # 49048B)	49048-1089	AR
SHOE,T=7.5 (Ref # 49048C)	49048-1090	8
SHOE,T=7.6 (Ref # 49048D)	49048-1091	AR
SHOE,T=7.7 (Ref # 49048E)	49048-1092	AR
SHOE,T=7.8 (Ref # 49048F)	49048-1093	AR
SHOE,T=7.9 (Ref # 49048G)	49048-1094	AR
SHOE,T=8.0 (Ref # 49048H)	49048-1095	AR
SPIDER (Ref # 49050)	49050-0003	1
CONVERTER-ASSY-DRIVE (Ref # 49093)	49093-0009	1
SHEAVE-MOVABLE (Ref # 59301)	59301-0001	1
SHEAVE-COMP,FIXED (Ref # 59302)	59302-0005	1
NUT,LOCK,6MM (Ref # 92019)	92019-008	8
PIN,8.2X10X14 (Ref # 92043)	92043-1264	2
PIN (Ref # 92043A)	92043-1699	4
BUSHING (Ref # 92139)	92139-0049	1
BUSHING (Ref # 92139A)	92139-0050	1
SPRING (Ref # 92145)	92145-0149	1
BOLT,12X163.5 (Ref # 92150)	92150-1008	1
WASHER (Ref # 92200)	92200-0249	2
WASHER (Ref # 92200A)	92200-1634	1