


1988 EX500

PARTS DIAGRAM

Swingarm

F2141-0053



1988 EX500

PARTS LIST

Swingarm

ITEM NAME	PART NUMBER	QUANTITY
ARM-COMP-SWING,SILVER NO.15 (Ref # 33001A)	33001-1300-X3	1
SHAFT-SWING ARM (Ref # 33032)	33032-1109	1
ADJUSTER-CHAIN (Ref # 33040)	33040-043	2
SLEEVE,14.1X22X220 (Ref # 42036)	42036-1212	1
GUARD,CHAIN (Ref # 55020)	55020-1218	1
BOLT,8X55 (Ref # 92002)	92002-1825	2
NUT,8MM (Ref # 92015)	92015-1364	2
NUT,14MM (Ref # 92015A)	92015-1407	1
BEARING-NEEDLE,22BTM 2820 (Ref # 92046)	92046-1036	2
SEAL-OIL,MHA22 28 5.7F (Ref # 92049)	92049-1254	2