


# 1992 Jet Mate

## PARTS DIAGRAM

### Tool

(F3182



# 1992 Jet Mate

## PARTS LIST

### Tool



| ITEM NAME                                  | PART NUMBER | QUANTITY |
|--------------------------------------------|-------------|----------|
| FUSE,20A,L=31.8 (Ref # 26006)              | 26006-3701  | 1        |
| FUSE,5A,L=31.8 (Ref # 26006A)              | 26006-3702  | 1        |
| TOOLKIT (Ref # 56007)                      | 56007-3708  | 1        |
| BAG,TOOL (Ref # 56008)                     | 56008-1007  | 1        |
| TOOL-DRIVER,#3PHILLIPS (Ref # 92107)       | 92107-005   | 1        |
| TOOL-DRIVER,#2PHILLIPS&SLOT (Ref # 92107A) | 92107-1051  | 1        |
| TOOL-WRENCH,ALLEN,5MM (Ref # 92110)        | 92110-1015  | 1        |
| TOOL-WRENCH,BOX,21MM (Ref # 92110A)        | 92110-1113  | 1        |
| TOOL-WRENCH,OPEN END,10X12 (Ref # 92110B)  | 92110-1152  | 1        |
| TOOL-WRENCH,OPEN END,14X17 (Ref # 92110C)  | 92110-1153  | 1        |
| TOOL-WRENCH,OPEN END,8X10 (Ref # 92110D)   | 92126-001   | 1        |
| TOOL-PLIERS (Ref # 92112)                  | 92112-003   | 1        |
| TOOL-WRENCH,ALLEN,8MM (Ref # 92127)        | 92127-002   | 1        |