



# 1985 KDX200

## PARTS LIST

### SWING ARM (KDX200-A3)

ITEM NAME	PART NUMBER	QUANTITY
CAP,SWING ARM (Ref # 11012)	11012-1355	2
CAP,SWING ARM (Ref # 11012A)	11012-1417	2
GUIDE-CHAIN,FR,UPP (Ref # 12053)	12053-1101	1
GUIDE-CHAIN,RR,INSIDE (Ref # 12053A)	12053-1105	1
GUIDE-CHAIN,RR (Ref # 12053B)	12053-1124	1
GUIDE-CHAIN (Ref # 12053C)	12053-1144	1
ARM-COMP-SWING (Ref # 33001)	33001-1232	1
SHAFT-SWING ARM (Ref # 33032)	33032-1042	2
ADJUSTER-CHAIN,LH (Ref # 33040)	33040-1060	2
SLEEVE,SWING ARM,L=40 (Ref # 42036)	42036-1145	2
NUT,14MM (Ref # 92015)	92015-1407	1
NUT-6MM (Ref # 92015A)	92015-1078	2
PIN (Ref # 92043)	92043-1110	2
BEARING-NEEDLE,TA2030 (Ref # 92046)	92046-1128	2
BOLT,FLANGED,6X45 (Ref # 130)	130G0645	2
SCREW CNTSNK HD 6X10 (Ref # 221)	221B0610	4
PIN COTTER 2.0X15 (Ref # 550)	550D2015	2