


# 1987 KX500

## PARTS DIAGRAM

### SWING ARM



# 1987 KX500

## PARTS LIST SWING ARM

| ITEM NAME                            | PART NUMBER | QUANTITY |
|--------------------------------------|-------------|----------|
| CAP,SWING ARM (Ref # 11012)          | 11012-1259  | 4        |
| CAP,CHAIN ADJUSTER (Ref # 11012A)    | 11012-1431  | 2        |
| GUIDE-CHAIN,RR,INSIDE (Ref # 12053)  | 12053-1105  | 1        |
| GUIDE-CHAIN,RR (Ref # 12053A)        | 12053-1179  | 1        |
| GUIDE-CHAIN,FR,LWR (Ref # 12053B)    | 12053-1208  | 1        |
| GUIDE-CHAIN,FR,UPP (Ref # 12053C)    | 12053-1213  | 1        |
| ARM-COMP-SWING (Ref # 33001)         | 33001-1276  | 1        |
| SHAFT-SWING ARM (Ref # 33032)        | 33032-1127  | 1        |
| ADJUSTER-CHAIN,OUTSID (Ref # 33040)  | 33040-1058  | 2        |
| ADJUSTER-CHAIN,INSIDE (Ref # 33040A) | 33040-1059  | 2        |
| SLEEVE,SWING ARM (Ref # 42036)       | 42036-1064  | 2        |
| GUARD,CALIPER (Ref # 55020)          | 55020-1247  | 1        |
| SCREW,6X14 (Ref # 92009)             | 92009-1287  | 2        |
| NUT,14MM (Ref # 92015)               | 92015-1407  | 1        |
| NUT-6MM (Ref # 92015A)               | 92015-1078  | 5        |
| NUT-8MM (Ref # 92015B)               | 92015-1143  | 2        |
| WASHER 6.5X20X1.6T (Ref # 92022)     | 92022-125   | 3        |
| BEARING-NEEDLE,TA2030 (Ref # 92046)  | 92046-1128  | 2        |
| BOLT-FLANGED-SMALL (Ref # 132)       | 132G0625    | 3        |
| SCREW CNTSNK HD 6X10 (Ref # 221)     | 221B0610    | 4        |
| SCREW,CONTRUNK HEAD (Ref # 221A)     | 221B0650    | 2        |
| NUT 8MM (Ref # 318)                  | 318G0800    | 2        |