


# 1981 KM100

## PARTS DIAGRAM

### TURN SIGNALS (KM100-A1~A4)



# 1981 KM100

## PARTS LIST

### TURN SIGNALS (KM100-A1~A4)

| ITEM NAME                       | PART NUMBER | QUANTITY |
|---------------------------------|-------------|----------|
| LAMP ASSY,TURN SIGNAL (Ref # 1) | 23040-038   | 4        |
| SCREW-PAN HEAD,4X20 (Ref # 2)   | 220E0420A   | 8        |
| LENS,TURN SIGNAL LAMP (Ref # 3) | 23048-1001  | 4        |
| LENS,TURN SIGNAL LAMP (Ref # 3) | 23048-1001  | 4        |
| GASKET-SIG LAMP LENS (Ref # 4)  | 23050-003   | 4        |
| BULB,6V 21CP (Ref # 5)          | 92069-056   | 4        |
| BOLT-UPSET (Ref # 6)            | 112G0630    | 4        |
| WASHER PLAIN 6MM (Ref # 7)      | 411B0600    | 8        |
| WASHER SPRING 6MM (Ref # 8)     | 461F0600    | 4        |
| BRACKET,TURN SIGNAL (Ref # 9)   | 23051-047   | 4        |
| WASHER PLAIN 12MM (Ref # 10)    | 411B1200    | 2        |
| WASHER SPRING 12MM (Ref # 11)   | 461F1200    | 4        |
| NUT-HEX-FINE,12MM (Ref # 12)    | 315B1200    | 2        |
| NUT-HEX-FINE,12MM (Ref # 13)    | 315B1200    | 2        |
| NUT 6MM (Ref # 14)              | 311B0600    | 4        |
| WASHER,PLAIN,12M/M (Ref # 15)   | 411D1200    | 2        |
| WASHER-PLAIN,4MM (Ref # 16)     | 23058-002   | 8        |