


1971 F7

PARTS DIAGRAM

CHASSIS ELECTRICAL EQUIPMENT



1971 F7

PARTS LIST

CHASSIS ELECTRICAL EQUIPMENT

ITEM NAME	PART NUMBER	QUANTITY
WIRING HARNESS-MAIN (Ref # 1)	26001-076	1
WIRING HARNESS-REAR (Ref # 2)	26002-029	1
LEAD WIRE (Ref # 3)	26011-042	1
FUSE ASSY (Ref # 4)	26004-017	1
FUSE 10A (Ref # 5)	26006-003	2
RELAY-TURN SIGNAL (Ref # 6)	27002-013	1
HORN (Ref # 7)	27003-061	1
SPRING BRAKE LAMP SW (Ref # 8)	27011-004	1
SWITCH-BRAKE LAMP (Ref # 9)	27010-018	1
YUA BAT 6N4-2A-5 (Ref # 10)	K26012-020	1
HOLDER,SPARE FUSE (Ref # 11)	26016-003	1
FUSE 10A (Ref # 12)	26006-003	2