

# 1972 Mach IV

## PARTS DIAGRAM

### TURN SIGNALS (H2-B/C)

NO IMAGE AVAILABLE

# 1972 Mach IV

## PARTS LIST

### TURN SIGNALS (H2-B/C)

| ITEM NAME                           | PART NUMBER | QUANTITY |
|-------------------------------------|-------------|----------|
| LAMP ASSY,TURN SIGNAL (Ref # 1)     | 23040-034   | 4        |
| SCREW-PAN HEAD,4X35 (Ref # 2)       | 220E0435A   | 8        |
| WASHER-PLAIN,4MM (Ref # 3)          | 23058-002   | 8        |
| LENS-SIGNAL LAMP (Ref # 4)          | 23048-1024  | 4        |
| LENS-SIGNAL LAMP (Ref # 4)          | 23048-1024  | 4        |
| GASKET,TURN SIG LAMP (Ref # 5)      | 23050-002   | 4        |
| BULB 12V 32CP (Ref # 6)             | 92069-055   | 4        |
| UNAVAILABLE IN PRICE BOOK (Ref # 7) | 110N0630-   | 4        |
| WASHER PLAIN 6MM (Ref # 8)          | 411B0600    | 8        |
| WASHER SPRING 6MM (Ref # 9)         | 461F0600    | 4        |
| NUT 6MM (Ref # 10)                  | 311B0600    | 4        |
| BRACKET-TURN SIG LAMP (Ref # 11)    | 23078-001   | 4        |
| BOLT SET-SIG LAMP BKT (Ref # 12)    | 23073-001   | 4        |
| DAMPER RUBBER (Ref # 13)            | 92075-128   | 4        |
| NUT 10MM (Ref # 14)                 | 315B1000    | 4        |
| DAMPER RUBBER,SIG LM (Ref # 15)     | 92075-158   | 2        |
| COLLAR (Ref # 16)                   | 23076-004   | 2        |
| WASHER SPRING 10MM (Ref # 17)       | 461F1000    | 2        |