


1978 KZ1000 LTD

PARTS DIAGRAM

CARBURETOR PARTS (KZ1000-B2)

Kawasaki
Let the Good Times Roll®



1978 KZ1000 LTD

PARTS LIST

CARBURETOR PARTS (KZ1000-B2)

ITEM NAME	PART NUMBER	QUANTITY
TOP,MIXING CHAMBER (Ref # 1)	16005-027	4
SCREW-PAN-WS-CROS (Ref # 2)	223B0414	12
WASHER SPRING 4MM (Ref # 3)	461F0400	28
GASKET,CHAMBER TOP (Ref # 4)	16019-031	4
NUT,5MM (Ref # 5)	16003-013	4
WASHER SPRING 5MM (Ref # 6)	461F0500	8
WASHER,PLAIN (Ref # 7)	16039-016	4
SCREW,SLOTTED (Ref # 8)	16046-012	4
SEAT,SPRING (Ref # 9)	16057-002	4
SPRING (Ref # 10)	16040-026	4
BOLT,HEX HEAD,5X14 (Ref # 11)	16067-006	4
LEVER,THROTTLE (Ref # 12)	39075-1001	4
SCREW,PAN HEAD,3X14 (Ref # 13)	16033-031	8
BRACKET,THROTTLE VLV (Ref # 14)	11034-1238	4
CIRCLIP (Ref # 15)	16008-010	4
JET NEEDLE,5CN7 (Ref # 16)	16009-1014	4
VALVE,THROTTLE,CAZ.0 (Ref # 17)	16025-1014	4
CIRCLIP (Ref # 18)	16076-003	4
COLLAR (Ref # 19)	16073-014	4
CAP,STARTER PLUNGER (Ref # 20)	16039-015	4
CAP,STARTER PLUNGER (Ref # 21)	16012-015	4
"O" RING,9MM (Ref # 22)	670B1509	4
SPRING,STARTER PLUG (Ref # 23)	16013-008	4
PLUNGER,STARTER (Ref # 24)	16016-021	4
NEEDLE JET,AO-3 (Ref # 25)	16017-1017	4
PIPE,BLEED (Ref # 26)	49122-1004	4
"O" RING,MAIN JET COV (Ref # 27)	16038-016	8
MAIN JET,#A102.5 (Ref # 28)	92063-1028	4
SPRING,PILOT SCREW (Ref # 29)	16022-016	4

1978 KZ1000 LTD

PARTS LIST

CARBURETOR PARTS (KZ1000-B2)

ITEM NAME	PART NUMBER	QUANTITY
SCREW,PILOT ADJUSTING (Ref # 30)	16014-018	4
"O" RING (Ref # 31)	16038-024	4
CAP,LIMITER (Ref # 32)	11012-1041	4
WASHER FLOAT VLV SEAT (Ref # 33)	16029-004	4
FLOAT VALVE ASSY (Ref # 34)	16030-027	4
PILOT JET,#A15 (Ref # 35)	92064-1017	4
FLOAT (Ref # 36)	16031-031	4
FLOAT PIN (Ref # 37)	16032-003	4
GASKET,FLOAT CHAMBER (Ref # 38)	11009-1563	4
SCREW PAN HEAD 4X16 (Ref # 39)	220B0416	16
SCREW,GUIDE (Ref # 40)	16049-007	4
RING,JET NEEDLE (Ref # 41)	92027-1103	1
SPRING,JET NEEDLE (Ref # 42)	92081-1072	4
PLATE,JET NEEDLE (Ref # 43)	13169-1107	4
WASHER,THROTTLE VALVE (Ref # 44)	92022-1024	4