


1980 KZ1300-B2

PARTS DIAGRAM

TURN SIGNALS



1980 KZ1300-B2

PARTS LIST

TURN SIGNALS

ITEM NAME	PART NUMBER	QUANTITY
SCREW-PAN HEAD,4X20 (Ref # 1)	220E0420A	8
LAMP ASSY,TURN SIGNAL (Ref # 2)	23037-1066	1
GASKET,TURN SIGNAL LP (Ref # 3)	11009-1139	1
LENS,TURN SIGNAL LAMP (Ref # 4)	23007-1021	1
SOCKET ASSY,TURN SIGN (Ref # 5)	23008-1045	2
BULB,12V 23/8W (Ref # 6)	92069-060	2
LAMP ASSY,TURN SIGNAL (Ref # 7)	23037-1067	1
GASKET,CLUTCH COVER (Ref # 8)	11009-1996	1
LENS,TURN SIGNAL LAMP (Ref # 9)	23007-1022	1
LAMP ASSY,TURN SIGNAL (Ref # 10)	23037-1068	1
GASKET,TURN SIGNAL LP (Ref # 11)	11009-1141	1
LENS,TURN SIGNAL LAMP (Ref # 12)	23007-1023	1
SOCKET ASSY,TURN SIGN (Ref # 13)	23008-1046	2
BULB 12V 32CP (Ref # 14)	92069-055	2
LAMP ASSY,TURN SIGNAL (Ref # 15)	23037-1069	1
GASKET,TURN SIGNAL LP (Ref # 16)	11009-1142	1
LENS,TURN SIGNAL LAMP (Ref # 17)	23007-1024	1
NUT 6MM (Ref # 18)	311B0600	4
WASHER SPRING 6MM (Ref # 19)	461F0600	4
WASHER PLAIN (Ref # 20)	92022-024	4