


1969 Mach III

PARTS DIAGRAM

TURN SIGNALS (H1/A OPTIONAL)

Kawasaki
Let the Good Times Roll®



(H1/

1969 Mach III

PARTS LIST

TURN SIGNALS (H1/A OPTIONAL)

ITEM NAME	PART NUMBER	QUANTITY
LAMP FRNT TURN SIGNAL (Ref # 1)	23040-020	4
LENS TURN SIGNAL LAMP (Ref # 2)	23048-011	4
BULB 12V 8W (Ref # 3)	92069-043	4
SCREW OVL CNTSNK 3X15 (Ref # 4)	222B0315A	8
NUT 10MM (Ref # 5)	315B1000	4
WASHER SPRING 10MM (Ref # 6)	461F1000	4
BRACKET TURN SIG LAMP (Ref # 7)	23051-011	2
COLLAR FUEL TANK FIT (Ref # 8)	92027-015	2
RELAY TURN SIGNAL (Ref # 9)	27002-008	1
BOLT-UPSET,6X16 (Ref # 10)	112G0616	1
WASHER PLAIN 6MM (Ref # 11)	411B0600	1
WASHER SPRING 6MM (Ref # 12)	461F0600	1
NUT 6MM (Ref # 13)	311B0600	1
BOLT,FLANGED,8X60 (Ref # 14)	92001-1581	1
BOLT,8X55 (Ref # 15)	92001-1386	1