

Starter Motor

Let the Good Times Roll®

Diagram illustrating the assembly of a generator, showing various components and their assembly points. The diagram includes a "FRONT" arrow indicating orientation.

Key components and assembly points labeled:

- Ref. Chassis Electrical Equipment**: Points to the main electrical connection area.
- Ref. Crankcase**: Points to the main engine housing.
- Ref. Generator**: Points to the generator assembly.
- Assembly Points (A)**: Indicated by circles with the letter "A", showing where components are mounted to the chassis or crankcase.
- Part Numbers**: Various components are labeled with numbers, including:
 - 26011, 92071, 92210, 13280, 26006, 27010, 26006, 21040, 21039, 92055A, 92055B, 92153, 92055, 92153, 92055A, 92153, 39076, 13107, 16085A, 13107, 16085, 92026, 13194, 92154, 21163, 92055A, 92015, 461, 120.

2013 ER-6n (European)

PARTS LIST

Starter Motor

ITEM NAME	PART NUMBER	QUANTITY
BOLT-SOCKET,6X10 (Ref # 120)	120CB0610	2
WASHER-SPRING,6MM (Ref # 461)	461DB0600	2
SHAFT,IDLE GEAR (Ref # 13107)	13107-1106	2
CLUTCH-ONEWAY (Ref # 13194)	13194-0015	1
HOLDER (Ref # 13280)	13280-0710	1
GEAR,67T (Ref # 16085)	16085-0076	1
GEAR,IDLE,28T (Ref # 16085A)	16085-0148	1
BRUSH,CARBON (Ref # 21039)	21039-0004	1
SPRING-BRUSH (Ref # 21040)	21040-0003	4
STARTER-ELECTRIC (Ref # 21163)	21163-0040	1
FUSE,BLADE,30A,GREEN (Ref # 26006)	26006-1006	2
WIRE-LEAD (Ref # 26011)	26011-0761	1
SWITCH,MAGNETIC (Ref # 27010)	27010-0709	1
LIMITER,16T&66T (Ref # 39076)	39076-0023	1
NUT,STARTER MOTOR (Ref # 92015)	92015-1476	1
SPACER,29.1X47.5X1.2 (Ref # 92026)	92026-087	1
RING-O (Ref # 92055)	92055-1276	1
RING-O,4.5X2.0 (Ref # 92055A)	92055-1370	3
RING-O,STARTER MOTOR (Ref # 92055B)	92055-1381	2
GROMMET (Ref # 92071)	92071-0024	1
BOLT (Ref # 92153)	92153-1783	2
BOLT,FLANGED,6X22 (Ref # 92154)	92154-0504	2
NUT,6MM (Ref # 92210)	92210-0188	1