

Starter Motor

Let the Good Times Roll®

Diagram illustrating the front view of a vehicle chassis assembly, showing various components and their assembly points. The diagram includes a "FRONT" arrow pointing left.

Key components and assembly points labeled include:

- Ref. Generator
- 92154
- 13194
- 92048
- 16085
- 13107
- 59051
- 21163
- 92055A
- 92055
- 92154A
- 13183
- 92200
- 92055B
- 92055B
- 26011
- 180
- 92071
- 92151
- 92144
- 11056
- 120
- 461
- Ref. Chassis Electrical Equipment
- 14092
- 26006A
- 26006
- 13091
- 27010

2014 Z1000 ABS

PARTS LIST

Starter Motor

ITEM NAME	PART NUMBER	QUANTITY
BRACKET (Ref # 11056)	11056-2770	1
BOLT-SOCKET,5X10 (Ref # 120)	120CB0510	2
HOLDER,MAGNETIC SWITCH (Ref # 13091)	13091-1884	1
SHAFT,IDLER GEAR (Ref # 13107)	13107-1377	1
PLATE (Ref # 13183)	13183-1460	1
CLUTCH-ONEWAY (Ref # 13194)	13194-1096	1
COVER (Ref # 14092)	14092-0109	1
GEAR,CLUTCH ONEWAY (Ref # 16085)	16085-0609	1
BOLT-UPSET-WS,5X10 (Ref # 180)	180BA0510	1
STARTER-ELECTRIC (Ref # 21163)	21163-0742	1
FUSE,MINI BLADE,15A,BLUE (Ref # 26006)	26006-0001	1
FUSE,MINI BLADE,30A,GREEN (Ref # 26006A)	26006-1080	1
WIRE-LEAD (Ref # 26011)	26011-0820	1
SWITCH (Ref # 27010)	27010-0770	1
WASHER-SPRING,5MM (Ref # 461)	461DB0500	2
GEAR-SPUR,IDLER (Ref # 59051)	59051-0741	1
RACE (Ref # 92048)	92048-0018	1
RING-O,STARTER (Ref # 92055)	92055-0013	2
RING-O,24.4X3.1 (Ref # 92055A)	92055-1262	1
RING-O (Ref # 92055B)	92055-1455	2
GROMMET (Ref # 92071)	92071-0031	1
SPRING,BRUSH (Ref # 92144)	92144-1423	4
BOLT,6X35 (Ref # 92151)	92151-1624	2
BOLT,TORX,6X14 (Ref # 92154)	92154-1225	6
BOLT,FLANGED (Ref # 92154A)	92154-1284	2
WASHER (Ref # 92200)	92200-1019	1