


# 1999 Prairie 300

## PARTS DIAGRAM

### Gear Change Mechanism

**Kawasaki**

Let the Good Times Roll®



# 1999 Prairie 300

## PARTS LIST

### Gear Change Mechanism

| ITEM NAME                                 | PART NUMBER | QUANTITY |
|-------------------------------------------|-------------|----------|
| BOLT-FLANGED,6X18 (Ref # 130)             | 130G0618    | 1        |
| BOLT-FLANGED,6X20 (Ref # 130A)            | 130P0620    | 1        |
| BOLT-FLANGED-SMALL,6X14 (Ref # 132)       | 132J0614    | 1        |
| BALL-STEEL,11/32" (Ref # 600)             | 600A1100    | 2        |
| BALL-STEEL,13/32" (Ref # 600A)            | 600A1300    | 1        |
| O RING,10MM (Ref # 670)                   | 670D1510    | 1        |
| GASKET,15.5X22X1 (Ref # 11009)            | 11009-1008  | 1        |
| GASKET,6.5X12X1.0 (Ref # 11009A)          | 11009-1568  | 1        |
| FORK-SHIFT (Ref # 13140)                  | 13140-1277  | 2        |
| SWITCH-COMP,NEUTRAL (Ref # 13151)         | 13151-1069  | 2        |
| LEVER-COMP (Ref # 13236)                  | 13236-1325  | 1        |
| LEVER-COMP,FORWARD/REVERSE (Ref # 13236A) | 13236-1327  | 1        |
| ROD-SHIFT (Ref # 49047)                   | 49047-1099  | 1        |
| PIN,4X34.8 (Ref # 92043)                  | 92043-1579  | 1        |
| BEARING-NEEDLE (Ref # 92046)              | 92046-1262  | 2        |
| GASKET,10.5X16X1 (Ref # 92065)            | 92065-058   | 2        |
| BUSHING-METER GEAR (Ref # 92087)          | 92087-1058  | 1        |
| SPRING,L=27.9 (Ref # 92145)               | 92145-1178  | 2        |
| SPRING (Ref # 92145A)                     | 92145-1216  | 1        |
| BOLT (Ref # 92151)                        | 92151-1451  | 1        |
| COLLAR (Ref # 92152)                      | 92152-1091  | 2        |