

Starter Motor

Let the Good Times Roll®

Exploded view diagram of a mechanical assembly. The diagram shows various components and their assembly relationships, with a 'FRONT' arrow indicating orientation.

Components and Part Numbers:

- 92055
- 92150
- 92055A
- 92022A
- 92055B
- 21025
- 92055B
- 92022
- 21025
- 21025
- 21025
- 21025
- 21163
- 130
- 92015A
- 21040
- 21040
- 92055A
- 21039
- 11012
- 26011
- 21017
- 92015A
- 39076
- 13194
- 92048
- 120
- 16085
- 27010
- 21064
- 92015

2000 Prairie 400 4X4

PARTS LIST

Starter Motor

ITEM NAME	PART NUMBER	QUANTITY
BOLT-SOCKET,8X16 (Ref # 120)	120P0816	6
BOLT-FLANGED,6X25 (Ref # 130)	130G0625	2
CAP,TERMINAL (Ref # 11012)	11012-1354	1
CLUTCH-ONEWAY (Ref # 13194)	13194-1094	1
GEAR,STARTER (Ref # 16085)	16085-1238	1
GROMMET,STARTER TERMINAL (Ref # 21017)	21017-017	1
WASHER,9.1X18X0.2 (Ref # 21025)	21025-011	4
BRUSH,CARBON (Ref # 21039)	21039-1063	1
SPRING-BRUSH (Ref # 21040)	21040-1057	2
DAMPER,MAGNETIC SWITCH (Ref # 21064)	21064-002	1
STARTER-ELECTRIC (Ref # 21163)	21163-1208	1
WIRE-LEAD,STARTER MOTOR (Ref # 26011)	26011-1648	1
SWITCH,MAGNETIC (Ref # 27010)	27010-1098	1
LIMITER,STARTER (Ref # 39076)	39076-1066	1
NUT,FLANGED,6MM (Ref # 92015)	92015-1193	2
NUT,STARTER MOTOR (Ref # 92015A)	92015-1476	2
WASHER,9.1X18X0.8 (Ref # 92022)	92022-1132	1
WASHER,LOCK,T=2.0 (Ref # 92022A)	92022-1458	2
RACE,ONE WAY CLUTCH (Ref # 92048)	92048-1090	1
RING-O (Ref # 92055)	92055-1276	1
RING-O,4.5X2.0 (Ref # 92055A)	92055-1370	3
RING-O,STARTER MOTOR (Ref # 92055B)	92055-1381	2
BOLT (Ref # 92150)	92150-1243	2