

# 2001 KX100


## PARTS DIAGRAM

### Swingarm

**Kawasaki**

Let the Good Times Roll®

F2141



# 2001 KX100

## PARTS LIST

### Swingarm

| ITEM NAME                            | PART NUMBER   | QUANTITY |
|--------------------------------------|---------------|----------|
| BOLT-FLANGED-SMALL (Ref # 132)       | 132G0650      | 2        |
| SCREW-PAN-CROS,5X8 (Ref # 220)       | 220B0508      | 4        |
| SCREW-CSK-CROS,6X45 (Ref # 221)      | 221B0645      | 2        |
| CAP (Ref # 11012)                    | 11012-1263    | 4        |
| GUIDE-CHAIN,RR,LH (Ref # 12053)      | 12053-1203    | 1        |
| GUIDE-CHAIN,RR,RH (Ref # 12053A)     | 12053-1204    | 1        |
| GUIDE-CHAIN,FR (Ref # 12053B)        | 12053-1414    | 1        |
| PLATE,GUIDE CHAIN (Ref # 13270)      | 13270-1829    | 1        |
| PLATE (Ref # 13270A)                 | 13270-1899    | 2        |
| ARM-COMP-SWING,SILVER (Ref # 33001A) | 33001-1543-TX | 1        |
| SHAFT-SWING ARM (Ref # 33032)        | 33032-1161    | 1        |
| ADJUSTER-CHAIN (Ref # 33040)         | 33040-1173    | 2        |
| SLEEVE,SWING ARM,L=34 (Ref # 42036)  | 42036-1067    | 2        |
| BOLT,8X46 (Ref # 92001)              | 92001-1179    | 2        |
| SCREW,5X10 (Ref # 92009)             | 92009-1828    | 4        |
| NUT,FLANGED,8MM (Ref # 92015)        | 92015-1014    | 2        |
| BEARING-NEEDLE (Ref # 92046)         | 92046-1046    | 2        |
| COLLAR (Ref # 92143)                 | 92143-1676    | 4        |
| NUT,LOCK,12MM (Ref # 92210)          | 92210-1249    | 1        |