


# 2003 Z1000

## PARTS DIAGRAM

### Transmission

**Kawasaki**

Let the Good Times Roll®



# 2003 Z1000

## PARTS LIST

### Transmission

| ITEM NAME                                  | PART NUMBER | QUANTITY |
|--------------------------------------------|-------------|----------|
| BALL-STEEL,5/32" (Ref # 600)               | 600A0500    | 3        |
| SHAFT-TRANSMISSION INPUT (Ref # 13127)     | 13127-0007  | 1        |
| SHAFT-TRANSMISSION OUTPUT (Ref # 13128)    | 13128-1260  | 1        |
| SPROCKET-OUTPUT,16T (Ref # 13144)          | 13144-1320  | 1        |
| GEAR,INPUT 2ND,17T (Ref # 13260)           | 13260-1681  | 1        |
| GEAR,OUTPUT 2ND,33T (Ref # 13260A)         | 13260-1686  | 1        |
| GEAR,OUTPUT 3RD,28T (Ref # 13260B)         | 13260-1880  | 1        |
| GEAR,OUTPUT 4TH,28T (Ref # 13260C)         | 13260-1881  | 1        |
| GEAR,OUTPUT LOW,36T (Ref # 13262)          | 13262-0029  | 1        |
| GEAR,OUTPUT 5TH,24T (Ref # 13262A)         | 13262-0030  | 1        |
| GEAR,INPUT 3RD&4TH,18T&21T (Ref # 13262B)  | 13262-0031  | 1        |
| GEAR,INPUT 5TH,20T (Ref # 13262C)          | 13262-0062  | 1        |
| GEAR,INPUT TOP,21T (Ref # 13262D)          | 13262-0074  | 1        |
| GEAR,OUTPUT TOP,23T (Ref # 13262E)         | 13262-0076  | 1        |
| GEAR,OUTPUT 4TH,28T (Ref # 13262F)         | 13262-0077  | 1        |
| WASHER,25.3X33X1 (Ref # 92022)             | 92022-1109  | 1        |
| WASHER,20.5X30X1,STEEL (Ref # 92022A)      | 92022-112   | 1        |
| BUSHING,INPUT 5TH GEAR (Ref # 92028)       | 92028-1735  | 1        |
| BUSHING,OUTPUT,2ND (Ref # 92028A)          | 92028-1739  | 1        |
| BUSHING,INPUT TOP GEAR (Ref # 92028B)      | 92028-1915  | 1        |
| BUSHING,OUTPUT,3RD&4TH (Ref # 92028C)      | 92028-1968  | 2        |
| RING-SNAP,20MM (Ref # 92033)               | 92033-015   | 2        |
| RING-SNAP,24MM (Ref # 92033A)              | 92033-026   | 3        |
| RING-SNAP,T=1.5 (Ref # 92033B)             | 92033-1249  | 3        |
| BEARING-BALL,DAC2557NSSH (Ref # 92045)     | 92045-0003  | 2        |
| BEARING-NEEDLE,K20X24X13 (Ref # 92046)     | 92046-1219  | 1        |
| BEARING-NEEDLE,PK20X27X17X3 (Ref # 92046A) | 92046-1303  | 2        |
| BUSHING,27X34X18.6 (Ref # 92139)           | 92139-1090  | 2        |
| COLLAR,SPROCKET (Ref # 92152)              | 92152-1466  | 1        |

# 2003 Z1000

## PARTS LIST

### Transmission



| ITEM NAME                           | PART NUMBER | QUANTITY |
|-------------------------------------|-------------|----------|
| WASHER (Ref # 92200)                | 92200-1065  | 1        |
| WASHER,25.2X31.0X1.5 (Ref # 92200A) | 92200-1239  | 2        |
| WASHER,20.5X31X1.5 (Ref # 92200B)   | 92200-1375  | 2        |
| WASHER,T=2.0 (Ref # 92200C)         | 92200-1457  | 3        |
| WASHER,OUTPUT 4TH (Ref # 92200D)    | 92200-1522  | 1        |
| WASHER,OUTPUT 3RD (Ref # 92200E)    | 92200-1523  | 1        |
| WASHER,INPUT (Ref # 92200F)         | 92200-1524  | 1        |
| NUT,SPROCKET (Ref # 92210)          | 92210-1098  | 1        |