

Transmission

Let the Good Times Roll®



2006 Z1000

PARTS LIST

Transmission

ITEM NAME	PART NUMBER	QUANTITY
BALL-STEEL,5/32" (Ref # 600)	600A0500	3
SHAFT-TRANSMISSION INPUT (Ref # 13127)	13127-0007	1
SHAFT-TRANSMISSION OUTPUT (Ref # 13128)	13128-1260	1
SPROCKET-OUTPUT,16T (Ref # 13144)	13144-1320	1
GEAR,INPUT 2ND,17T (Ref # 13260)	13260-1681	1
GEAR,OUTPUT 2ND,33T (Ref # 13260A)	13260-1686	1
GEAR,OUTPUT 3RD,28T (Ref # 13260B)	13260-1880	1
GEAR,OUTPUT LOW,36T (Ref # 13262)	13262-0029	1
GEAR,OUTPUT 5TH,24T (Ref # 13262A)	13262-0030	1
GEAR,INPUT 3RD&4TH,18T&21T (Ref # 13262B)	13262-0031	1
GEAR,INPUT 5TH,20T (Ref # 13262C)	13262-0062	1
GEAR,OUTPUT 4TH,28T (Ref # 13262D)	13262-0077	1
GEAR,INPUT TOP,21T (Ref # 13262E)	13262-0228	1
GEAR,OUTPUT TOP,23T (Ref # 13262F)	13262-0229	1
WASHER,25.3X33X1 (Ref # 92022)	92022-1109	1
WASHER,20.5X30X1,STEEL (Ref # 92022A)	92022-112	1
BUSHING,INPUT 5TH GEAR (Ref # 92028)	92028-1735	1
BUSHING,OUTPUT,2ND (Ref # 92028A)	92028-1739	1
BUSHING,INPUT TOP GEAR (Ref # 92028B)	92028-1915	1
BUSHING,OUTPUT,3RD&4TH (Ref # 92028C)	92028-1968	2
RING-SNAP,20MM (Ref # 92033)	92033-015	2
RING-SNAP,24MM (Ref # 92033A)	92033-026	3
RING-SNAP,T=1.5 (Ref # 92033B)	92033-1249	3
BEARING-BALL,DAC2557NSSH (Ref # 92045)	92045-0003	2
BEARING-NEEDLE,K20X24X13 (Ref # 92046)	92046-1219	1
BEARING-NEEDLE,PK20X27X17X3 (Ref # 92046A)	92046-1303	2
BUSHING,27X34X18.6 (Ref # 92139)	92139-1090	2
COLLAR,SPROCKET (Ref # 92152)	92152-1466	1
WASHER (Ref # 92200)	92200-1065	1

2006 Z1000

PARTS LIST

Transmission



ITEM NAME	PART NUMBER	QUANTITY
WASHER,25.2X31.0X1.5 (Ref # 92200A)	92200-1239	2
WASHER,20.5X31X1.5 (Ref # 92200B)	92200-1375	2
WASHER,T=2.0 (Ref # 92200C)	92200-1457	3
WASHER,OUTPUT 4TH (Ref # 92200D)	92200-1522	1
WASHER,OUTPUT 3RD (Ref # 92200E)	92200-1523	1
WASHER,INPUT (Ref # 92200F)	92200-1524	1
NUT,SPROCKET (Ref # 92210)	92210-1098	1