


# 1996 1100 ZXi PARTS DIAGRAM

Generator

E1810



## 1996 1100 ZXi PARTS LIST

### Generator

| ITEM NAME                        | PART NUMBER | QUANTITY |
|----------------------------------|-------------|----------|
| BOLT-SOCKET,6X30 (Ref # 120)     | 120P0630    | 3        |
| CAP (Ref # 11012)                | 11012-3005  | 2        |
| CAP,ELECTRIC CASE (Ref # 11012A) | 11012-3761  | 1        |
| STATOR (Ref # 21003)             | 21003-3730  | 1        |
| ROTOR,MAGNETO (Ref # 21007)      | 21007-3722  | 1        |
| CONNECTOR-CORD (Ref # 59221)     | 59221-3703  | 1        |
| CONNECTOR-CORD (Ref # 59221A)    | 59221-506   | 1        |
| BOLT,6X35 (Ref # 92002)          | 92002-3715  | 2        |
| SCREW,5X12 (Ref # 92009)         | 92009-1296  | 4        |
| SPACER,6.3X12X1.0 (Ref # 92026)  | 92026-094   | 3        |
| KEY,WOODRUFF (Ref # 92038)       | 92038-001   | 1        |
| RING-O (Ref # 92055)             | 92055-3706  | 1        |
| GROMMET (Ref # 92071)            | 92071-3784  | 1        |
| GROMMET (Ref # 92071A)           | 92071-3804  | 1        |
| BOLT (Ref # 92150)               | 92150-3843  | 1        |