


# 1999 1100 STX PARTS DIAGRAM

Ignition System(JT1100-B2)



# 1999 1100 STX PARTS LIST

Ignition System(JT1100-B2)

| ITEM NAME                           | PART NUMBER | QUANTITY |
|-------------------------------------|-------------|----------|
| CAP (Ref # 11012)                   | 11012-3005  | 6        |
| CAP,HOLDER (Ref # 11012A)           | 11012-3768  | 3        |
| CAP (Ref # 11012B)                  | 11012-3791  | 1        |
| BRACKET (Ref # 11048)               | 11048-3770  | 1        |
| HOLDER (Ref # 13091)                | 13091-3785  | 1        |
| HOLDER (Ref # 13091A)               | 13091-3800  | 1        |
| HOLDER (Ref # 13091B)               | 13091-3804  | 1        |
| HOLDER-ASSY (Ref # 14079)           | 14079-3710  | 1        |
| REGULATOR-VOLTAGE (Ref # 21066)     | 21066-3712  | 1        |
| IGNITER (Ref # 21119)               | 21119-3755  | 1        |
| COIL-IGNITION,#1 (Ref # 21121)      | 21121-3708  | 1        |
| COIL-IGNITION,#2 (Ref # 21121A)     | 21121-3709  | 1        |
| COIL-IGNITION,#3 (Ref # 21121B)     | 21121-3710  | 1        |
| CAP-SPARK PLUG (Ref # 21130)        | 21130-3706  | 3        |
| FUSE-ASSY (Ref # 26004)             | 26004-3719  | 1        |
| FUSE,10A-R (Ref # 26006)            | 26006-1007  | 2        |
| FUSE,3A-P (Ref # 26006A)            | 26006-1060  | 2        |
| HARNESS,SUB (Ref # 26030)           | 26030-3723  | 1        |
| HARNESS (Ref # 26030A)              | 26030-3724  | 1        |
| SWITCH (Ref # 27010)                | 27010-3744  | 1        |
| SWITCH (Ref # 27010A)               | 27010-3759  | 1        |
| SWITCH,STARTER RELAY (Ref # 27010B) | 27010-3760  | 1        |
| JOINT (Ref # 59071)                 | 59071-3001  | 6        |
| CASE-ELECTRIC,UPP (Ref # 59416)     | 59416-3755  | 1        |
| CASE-ELECTRIC,LWR (Ref # 59416A)    | 59416-3759  | 1        |
| BOLT,6X25 (Ref # 92002)             | 92002-3714  | 8        |
| BOLT,6X16 (Ref # 92002A)            | 92002-3728  | 2        |
| BOLT,6X20 (Ref # 92002B)            | 92002-3755  | 1        |
| WASHER (Ref # 92022)                | 92022-3035  | 2        |

# 1999 1100 STX PARTS LIST

Ignition System(JT1100-B2)

| ITEM NAME                                 | PART NUMBER | QUANTITY |
|-------------------------------------------|-------------|----------|
| WASHER,6.2X20X2 (Ref # 92022A)            | 92022-3714  | 2        |
| SPACER (Ref # 92026)                      | 92026-3703  | 2        |
| CLAMP (Ref # 92037)                       | 92037-1173  | 6        |
| CLAMP,HOSE (Ref # 92037A)                 | 92037-1603  | 3        |
| RING-O (Ref # 92055)                      | 92055-1292  | 1        |
| RING-O,ELECTRIC (Ref # 92055A)            | 92055-3738  | 1        |
| PLUG-SPARK,BR9ES(NGK),SOLID (Ref # 92070) | 92070-1157  | 3        |
| GROMMET (Ref # 92071)                     | 92071-3004  | 2        |
| GROMMET (Ref # 92071A)                    | 92071-3786  | 1        |
| GROMMET (Ref # 92071B)                    | 92071-3804  | 2        |
| GROMMET (Ref # 92071C)                    | 92071-527   | 3        |
| BAND (Ref # 92072)                        | 92072-3778  | 2        |
| BOLT-WP,6X14 (Ref # 156)                  | 156R0614    | 1        |
| BOLT-WP,6X20 (Ref # 156A)                 | 156R0620    | 5        |
| BOLT-WP (Ref # 156B)                      | 156R0690    | 4        |
| NUT-HEX,6MM (Ref # 311)                   | 311R0600    | 4        |
| WASHER-PLAIN-SMALL,10MM (Ref # 410)       | 410B1000    | 2        |
| WASHER-PLAIN-SMALL,6MM (Ref # 410A)       | 410S0600    | 2        |
| O RING,16MM (Ref # 670)                   | 670B2016    | 6        |
| BOLT,SOCKET,6X18 (Ref # 92150)            | 92150-3775  | 4        |
| TUBE,HIGH TENSION,L=330 (Ref # 92190)     | 92190-3707  | 1        |
| TUBE,8X10X565 (Ref # 92190A)              | 92190-3942  | 1        |
| TUBE,8X10X425 (Ref # 92190B)              | 92190-3943  | 1        |