


## 1980 KX420 PARTS DIAGRAM

SWING ARM (KX420-A2)



# 1980 KX420 PARTS LIST

## SWING ARM (KX420-A2)

| ITEM NAME                      | PART NUMBER | QUANTITY |
|--------------------------------|-------------|----------|
| SHAFT-SWING ARM (Ref # 1)      | 33032-1020  | 1        |
| SLEEVE,SWING ARM (Ref # 2)     | 42036-1031  | 2        |
| NUT-LOCK,14MM (Ref # 3)        | 92019-011   | 1        |
| SWING ARM (Ref # 4)            | 33001-4003  | 1        |
| CAP,SWING ARM (Ref # 5)        | 11012-1099  | 4        |
| SHIM,SWING ARM (Ref # 6)       | 92025-1116  | 4        |
| BUSHING (Ref # 7)              | 92028-1072  | 2        |
| GUIDE,CHAIN (Ref # 8)          | 12053-4001  | 1        |
| SCREW,6X20 (Ref # 9)           | 92009-1289  | 2        |
| COLLAR (Ref # 10)              | 92027-1260  | 2        |
| NUT-6MM (Ref # 11)             | 92015-1078  | 2        |
| GUARD,CHAIN (Ref # 12)         | 55020-4009  | 1        |
| GUARD,CHAIN (Ref # 13)         | 55020-4010  | 1        |
| GUIDE,CHAIN (Ref # 14)         | 12053-1015  | 2        |
| BOLT-UPSET (Ref # 15)          | 112G0660    | 3        |
| WASHER PLAIN 6MM (Ref # 16)    | 411B0600    | 10       |
| BOLT-UPSET (Ref # 17)          | 112G0645    | 2        |
| NUT (Ref # 18)                 | 92019-008   | 5        |
| COLLAR (Ref # 19)              | 92027-4016  | 1        |
| COLLAR (Ref # 20)              | 92027-4017  | 2        |
| ADJUSTER,CHAIN (Ref # 21)      | 33040-4004  | 2        |
| NUT 8MM (Ref # 22)             | 318G0800    | 2        |
| BOLT,CHAIN ADJUSTER (Ref # 23) | 92001-1027  | 2        |