


# 1989 KE100 PARTS DIAGRAM

Electrical Equipment



# 1989 KE100 PARTS LIST

## Electrical Equipment

| ITEM NAME                                 | PART NUMBER | QUANTITY |
|-------------------------------------------|-------------|----------|
| HARNESS,TAIL LAMP (Ref # 26001)           | 26001-1007  | 1        |
| HARNESS,MAIN (Ref # 26001A)               | 26001-1275  | 1        |
| FUSE-ASSY (Ref # 26004)                   | 26004-1010  | 1        |
| FUSE,10A,L=30 (Ref # 26006)               | 26006-1002  | 1        |
| FUSE,15A,L=30 (Ref # 26006A)              | 26006-1003  | 1        |
| WIRE-LEAD (Ref # 26011)                   | 26011-093   | 1        |
| BATTERY,6V 6AH,6N6-1D-2(K1) (Ref # 26012) | 26012-1193  | 1        |
| RELAY-ASSY,TURN SIGNAL (Ref # 27002)      | 27002-013   | 1        |
| HORN (Ref # 27003)                        | 27003-1052  | 1        |
| BAND,L=123 (Ref # 92072)                  | 92072-030   | 6        |
| BAND,L=149 (Ref # 92072A)                 | 92072-031   | 2        |
| BAND,L=218 (Ref # 92072B)                 | 92072-032   | 3        |
| BAND,L=186 (Ref # 92072C)                 | 92072-056   | 1        |
| BOLT-UPSET-WS,6X25 (Ref # 180)            | 180C0625    | 2        |