

## 1981 KZ440 Belt PARTS DIAGRAM

TURN SIGNALS (F/NO.002101-002300) ('81-')

NO IMAGE AVAILABLE

## 1981 KZ440 Belt PARTS LIST

TURN SIGNALS (F/NO.002101-002300) ('81-'

ITEM NAME	PART NUMBER	QUANTITY
GASKET,TURN SIGNAL (Ref # 11009)	11009-1052	1
LAMP ASSY,TURN SIGNAL (Ref # 23040)	23040-1018	1
LENS-SIGNAL LAMP (Ref # 23048)	23048-1022	1
BRACKET,TURN SIGNAL (Ref # 23051)	23051-1014	1
BRACKET FR SGNL LAMP (Ref # 23051A)	23051-1032	1
NUT,FLANGED,10MM (Ref # 92015)	92015-1428	1
COLLAR (Ref # 92027)	92027-147	1
BULB 12V 32CP (Ref # 92069)	92069-055	1
WASHER-PLAIN,4MM (Ref # 92075)	23058-002	1
DAMPER RUBBER (Ref # 92075A)	92075-128	1
DAMPER RUBBER,SIG LM (Ref # 92075B)	92075-158	1
BOLT-UPSET (Ref # 110)	112G0630	1
SCREW-PAN-CRROSS,4X12 (Ref # 220)	220B0412	1
NUT 6MM (Ref # 311)	311B0600	1
WASHER PLAIN 6MM (Ref # 411)	411B0600	1
WASHER-PLAIN,10MM (Ref # 411A)	411D1000	1
WASHER SPRING 6MM (Ref # 461)	461F0600	1