


1985 Tecate® PARTS DIAGRAM

SWING ARM ('85 A2)

F2140-0196



1985 Tecate® PARTS LIST

SWING ARM ('85 A2)

ITEM NAME	PART NUMBER	QUANTITY
CAP,SWING ARM (Ref # 11012)	11012-1259	1
GUIDE-CHAIN,BLACK (Ref # 12053)	12053-4003	1
ARM-SWING (Ref # 33001)	33001-1228	1
SHAFT-SWING ARM (Ref # 33032)	33032-1042	1
ADJUSTER-CHAIN (Ref # 33040)	33040-4006	1
SLEEVE,SWING ARM (Ref # 42036)	42036-1064	1
SCREW,6X18 (Ref # 92009)	92009-1111	1
NUT,14MM (Ref # 92015)	92015-1407	1
COLLAR (Ref # 92027)	92027-164	1
BRG,NEEDLE,HMK2030 (Ref # 92046)	92046-1031	1
BOLT-UPSET-WSP (Ref # 187)	187B0620	1
NUT 8MM (Ref # 318)	318G0800	1
WASHER PLAIN 8MM (Ref # 411)	411B0800	1