


1987 KX™500 PARTS DIAGRAM

SHOCK ABSORBER

F2280-0043



1987 KX™500 PARTS LIST

SHOCK ABSORBER

ITEM NAME	PART NUMBER	QUANTITY
CAP,VALVE AIR (Ref # 11012)	11012-1391	1
GUIDE,SPRING (Ref # 13070)	13070-1161	1
GUIDE,SPRING (Ref # 13070A)	13070-1165	1
CYLINDER-SHOCKABSORBE (Ref # 43089)	43089-1119	1
SHOCKABSORBER (Ref # 45014)	45014-1357	1
ROD,SHOCKABSORBER (Ref # 46102)	46102-1199	1
JOINT-BALL,REAR SHOCK (Ref # 59266)	59266-1053	1
BOLT (Ref # 92002)	92002-1955	1
NUT,SPRING ADJUST (Ref # 92015)	92015-1556	1
NUT,SPRING ADJUST LOC (Ref # 92015A)	92015-1557	1
BUSHING,ROD (Ref # 92028)	92028-1473	1
RING-SNAP,REARSHOCK (Ref # 92033)	92033-1090	1
RING-SNAP,SHOCKABSORB (Ref # 92033A)	92033-1228	1
SEAL-OIL (Ref # 92049)	92049-1281	1
RING-O,ROD (Ref # 92055)	92055-1369	1
RING-O (Ref # 92055A)	92055-1383	1
BUSHING-RUBBER,SHOCKA (Ref # 92092)	92092-1062	1
SEAL,REAR SHOCK (Ref # 92093)	92093-1183	1
COLLAR,SHOCKABSORBER (Ref # 92143)	92143-1116	1
SPRING,SHOCKABSORBER, (Ref # 92144)	92144-1089	1
SPRING,SHOCKABSORBER, (Ref # 92144A)	92144-1132	1
SPRING,SHOCKABSORBER, (Ref # 92144B)	92144-1135	1