


1987 KX™500 PARTS DIAGRAM

LABELS

F2869-0541



1987 KX™500 PARTS LIST

LABELS

ITEM NAME	PART NUMBER	QUANTITY
EMBLEM,SHROUD,LH (Ref # 56014)	56014-1166	1
EMBLEM,SHROUD,RH (Ref # 56014A)	56014-1167	1
MARK (Ref # 56018)	56018-1651	1
MARK,SWING ARM,UNI-TR (Ref # 56018A)	56018-1910	1
LABEL,NOISE (Ref # 56040)	56040-1101	1
LABEL-WARNING,GASOLIN (Ref # 56040A)	56040-1129	1