


1977 KZ400 Deluxe PARTS DIAGRAM

TURN SIGNALS



1977 KZ400 Deluxe PARTS LIST

TURN SIGNALS

ITEM NAME	PART NUMBER	QUANTITY
BOLT-UPSET (Ref # 1)	112G0630	1
WASHER PLAIN 6MM (Ref # 2)	410B0600	1
LAMP-TURN SIGNAL (Ref # 3)	23040-029	1
WASHER SPRING 6MM (Ref # 4)	461F0600	1
NUT 6MM (Ref # 5)	311B0600	1
BKT TURN SIGNL LIGHT (Ref # 6)	23051-049	1
CAP,SIGNAL LIGHT STAY (Ref # 7)	92102-015	1
COLLAR (Ref # 8)	92027-281	1
BRACKET,TURN SIG LAMP (Ref # 9)	23051-054	1
DAMPER RUBBER,SIGNAL (Ref # 10)	92075-238	1
CAP,FR SIG LIGHT STAY (Ref # 11)	92102-014	1
WIRE TURN SIGNAL LEAD (Ref # 12)	26011-081	1
NUT-HEX-FINE,12MM (Ref # 13)	315B1200	1
DAMPER RUBBER,SIGNAL (Ref # 14)	92075-241	1
COLLAR,RR SIG LIGHT (Ref # 15)	92027-225	1
CAP,RR SIG LIGHT STAY (Ref # 16)	92102-013	1
WASHER PLAIN 12MM (Ref # 17)	411B1200	1
BULB 12V 32CP (Ref # 18)	92069-055	1
GASKET,TURN SIG LAMP (Ref # 19)	23050-002	1
LENS-SIGNAL LAMP (Ref # 20)	23048-1024	2
WASHER-PLAIN,4MM (Ref # 21)	23058-002	1
SCREW-PAN HEAD,4X35 (Ref # 22)	220E0435A	1
WASHER SPRING 12MM (Ref # 23)	461F1200	1
BOLT,HEX HEAD,12X45 (Ref # 24)	113B1245A	1
NUT 12MM (Ref # 25)	92020-014	1