


1976 KZ400 Standard PARTS DIAGRAM

TURN SIGNALS ('76-'77 KZ400 - D3/D4)



101

1976 KZ400 Standard PARTS LIST

TURN SIGNALS ('76-'77 KZ400 - D3/D4)

| ITEM NAME | PART NUMBER | QUANTITY |
|----------------------------------|-------------|----------|
| BOLT HEX HEAD 6X36 (Ref # 1) | 110N0636 | 1 |
| WASHER,PLAIN,6MM (Ref # 2) | 410D0600 | 1 |
| LAMP-TURN SIGNAL (Ref # 3) | 23040-029 | 1 |
| WASHER SPRING 6MM (Ref # 4) | 461F0600 | 1 |
| NUT 6MM (Ref # 5) | 312B0600 | 1 |
| BKT TURN SIGNL LIGHT (Ref # 6) | 23051-049 | 1 |
| CAP,SIGNAL LIGHT STAY (Ref # 7) | 92102-015 | 1 |
| COLLAR,FR SIG LIGHT (Ref # 8) | 92027-223 | 1 |
| DAMPER RUBBER,SIG LM (Ref # 9) | 92075-158 | 2 |
| DAMPER RUBBER,SIGNAL (Ref # 10) | 92075-238 | 1 |
| CAP,FR SIG LIGHT STAY (Ref # 11) | 92102-014 | 1 |
| WIRE TURN SIGNAL LEAD (Ref # 12) | 26011-081 | 1 |
| NUT-HEX-FINE,12MM (Ref # 13) | 315B1200 | 1 |
| DAMPER RUBBER,SIGNAL (Ref # 14) | 92075-241 | 1 |
| COLLAR,RR SIG LIGHT (Ref # 15) | 92027-225 | 1 |
| CAP,RR SIG LIGHT STAY (Ref # 16) | 92102-013 | 1 |
| WASHER PLAIN 12MM (Ref # 17) | 411B1200 | 1 |
| BULB 12V 32CP (Ref # 18) | 92069-055 | 1 |
| GASKET,TURN SIG LAMP (Ref # 19) | 23050-002 | 1 |
| LENS-SIGNAL LAMP (Ref # 20) | 23048-1024 | 2 |
| WASHER-PLAIN,4MM (Ref # 21) | 23058-002 | 1 |
| SCREW-PAN HEAD,4X35 (Ref # 22) | 220E0435A | 1 |