


1981 305 CSR PARTS DIAGRAM

CABLES



F2540-0034



1981 305 CSR PARTS LIST

CABLES

ITEM NAME	PART NUMBER	QUANTITY
GASKET,TACHOMETER GER (Ref # 11009)	92065-103	1
CABLE,SPEEDOMETER (Ref # 54001)	54001-1012	1
CABLE-CLUTCH (Ref # 54011A)	54011-1092	1
CABLE-THROTTLE,OPEN (Ref # 54012)	54012-1100	1
CABLE,TACHOMETER (Ref # 54018)	54018-1002	1
CLAMP,TACHOMETER CABL (Ref # 92037)	92037-1259	1
BAND,WIRING HARNESS (Ref # 92072)	92072-056	1