


## 1968 PARTS DIAGRAM

CABLES



## 1968 PARTS LIST

### CABLES

ITEM NAME	PART NUMBER	QUANTITY
CABLE,SPEEDOMETER (Ref # 1)	54001-028	2
CABLE CLTCH (Ref # 2)	54011-029	1
CABLE CONTROL (Ref # 3)	54012-036	1
CABLE FRONT BRAKE (Ref # 4)	54005-037	3
CABLE STARTER (Ref # 5)	54017-017	1
CLAMP-CABLE (Ref # 6)	92037-069	1
BAND RUBBER (Ref # 7)	92072-013	1