


## 2000 Super Sherpa® PARTS DIAGRAM

Turn Signals



## 2000 Super Sherpa® PARTS LIST

Turn Signals

ITEM NAME	PART NUMBER	QUANTITY
GASKET,TURN SIGNAL LAMP LENS (Ref # 11009)	11009-1128	1
CAP,SIGNAL LAMP (Ref # 11012)	11012-1367	1
LAMP-ASSY-SIGNAL,FR (Ref # 23037)	23037-1201	1
LAMP-ASSY-SIGNAL,RR (Ref # 23037A)	23037-1371	1
LENS-SIGNAL LAMP (Ref # 23048)	23048-1076	1
BRACKET-SIGNAL LAMP,RR (Ref # 23051)	23051-1246	1
WASHER,PLAIN,4MM (Ref # 23058)	23058-002	1
SCREW,TAPPING,4X30 (Ref # 92009)	92009-1056	1
NUT,FLANGED,10MM (Ref # 92015)	92015-1428	1
BULB,12V 32CP(23W) (Ref # 92069)	92069-055	1
BOLT,FLANGED,6X16 (Ref # 92150)	92150-1506	1